

# We Can Now Unlock - LG 2G All Models All Hardware/Software versions! Even KS360 & KP501/ KP502 !

Contributed by Administrator  
Monday, 09 August 2004  
Last Updated Wednesday, 11 August 2010

We are pleased to announce that we can now offer Unlocking Services on all LG 2G / Infinion Models & All Hardware/Software versions!

We are the first and only place in Torbay to offer this service for only £15 which includes the cost of the server credits to do the unlock/debrand and the Unlock itself.

The full LG List is below:

LG KC780  
KM900  
KB770  
KF701  
MS25  
KU990MF  
LG F9200  
LG MG270  
KP501  
U370  
U370W  
U370C  
KF390  
KF390Q  
KP570Q  
KF690  
LG KP170  
LG KP175  
LG KP500  
MU515,  
KF310,  
KB620,  
HB620,  
KF700,  
KC910,  
CU915,  
CU920,  
TU915,  
LG CP150  
LG KP150  
LG KP151  
LG KP152  
LG KP260  
LG KP265  
LG KM710  
KS360  
KP220  
KM380,  
KM385,  
KM386,  
KC550,  
KF510,  
KF240,  
KF245,  
KF300,  
KP135,  
KF600,  
KP110,  
KP115,

KP230,  
KP233,  
KP2350,  
KM500,  
KU990R,  
KE990  
KS20  
KP100,  
KP105,  
KP106  
KU380,  
KU450,  
KU990,  
U990,  
CU515,  
TU515,  
CU575,  
TU575,  
CU720,  
TU720,  
CG180  
CE110  
LG240,  
ME240q,  
KG98,  
KG195,  
KG228,  
KG248,  
KG328,  
KG338,  
TG300,  
TG800,  
TG800F,  
KG296,  
MG295  
MG296.  
KE608,  
KE858,  
KG70,  
KG77,  
KG271,  
KG276,  
KG278,  
KG285,  
KG288,  
KG289,  
KG370,  
KG375,  
MG370,  
CU500V  
TU500  
TU500F  
KU830  
MG160  
KG270  
KG275  
KG330  
KG290  
KG291i  
CU320 - direct unlock,flashing,repairing,phone reset  
CU400 - FULL SUPPORT  
TU500 - FULL SUPPORT  
MU500 - FULL SUPPORT  
CU405 - FULL SUPPORT  
CU500 - FULL SUPPORT

KU250 - DIRECT UNLOCK, flashing,repairing,phone reset  
KU311 - direct unlock,flashing,repairing,phone reset  
KU800 - direct unlock,flashing,repairing,phone reset  
KU970 - direct unlock,flashing,repairing,phone reset  
L600V - direct unlock,flashing,repairing,phone reset  
U250 - DIRECT UNLOCK, flashing,repairing,phone reset  
U300 - temp.unlock(64k and 128k SIM supported),flashing,repairing,phone reset  
U310 - flashing,repairing,phone reset  
U8150 - direct unlock,unlock code reading,phone reset  
U8210 - direct unlock,flashing,repairing,phone reset  
U8290 - direct unlock,flashing,repairing,phone reset  
U830 - unlock by patched flash,flashing,repairing,phone reset  
U8500 - unlock by patched flash,flashing,repairing,phone reset  
U880 - temp.unlock(64k and 128k SIM supported),flashing,repairing,phone reset  
U890 - temp.unlock(64k and 128k SIM supported),flashing,repairing,phone reset  
U900 - temp.unlock(128k SIM supported),flashing,repairing,phone reset  
U960  
U970  
KG280  
KG130,  
KP200,  
KP202,  
MG225,  
MG230,  
MG235  
MG280  
KE260,  
KE360,  
KE600,  
KE770,  
KE800,  
KE820,  
KE 850 / LG PRADA  
KE970 / LG SHINE  
ME970  
LG-B2060  
LG-MG125  
LG-KG300  
Lg-KG920  
Lg-KG928  
LG-S5100  
LG-MG120  
LG-G1800  
LG-C2500  
LG-KG190  
LG-KG200  
LG-M300  
LG-CG225  
LG-F7200  
LG-Cg300  
LG-F1200  
LG-Kg810  
LG-Mg810  
LG-Mg530  
LG-MG155  
LG-TG800  
LG-KG800  
LG-MG800  
LG-KG90  
LG-KG320  
LG-ME591.  
LG-G7120  
LG-F2250  
LG-F3000  
LG-MG100

LG-ME500  
LG-KG210  
LG-KG225  
LG-KG220  
LG-U8550  
LG-U8290  
LG-U8210  
LG-U8150  
LG-U8380  
LG-U8360  
LG-U8180  
LG-U8330  
LG-CE500  
LG-MG105  
LG-M6100  
LG-T5100  
LG-C1500  
LG-MG200  
LG-M6100  
LG-MG105  
LG-A7110  
LG-A7150  
LG-B2070  
LG-B2150  
LG-B2250  
LG-C1150  
LG-C1300i  
LG-LG1300i  
LG-C3380  
LG-L1400  
LG-F9100  
LG-M4410  
LG-MG191  
LG-P7200  
LG-S5000  
LG-S5200  
LG-F2200  
LG-G7200  
LG-L1200  
LG-L342i  
LG-L341  
LG-F2400  
LG-B2100  
LG-C2100  
LG-C3320  
LG-F2100  
LG-F2300  
LG-F7250  
LG-C3300  
LG-C3310  
LG-C3400  
LG-B2000  
LG-B2050  
LG-L5100  
LG-L3100  
LG-C2200  
LG-U8110  
LG-U8120  
LG-U8130 also R version  
LG-U8138  
- LG-L1100  
- LG-B1200  
- LG-B1300  
- LG-C1100  
- LG-C1200

- LG-C1400
- LG-G510
- LG-G1500
- LG-G1600
- LG-W3000
- LG-GW3100
- LG-C3100
- LG-G4010
- LG-G4050
- LG-GW5200
- LG-GW5220
- LG-GW5300-5310
- LG-GW5400
- LG-G5500
- LG-G7000
- LG-G7020
- LG-G7030
- LG-G7050
- LG-G7070
- LG-G7100-7120
- Alcatel OT320